

## Opacity Tester



The Q-Card opacity tester is designed as a go/no-go opacity test for ISO and MasterCard CQM standards. To test a card, the unit utilizes a calibration card to establish the baseline opacity criteria. The card under test will be evaluated against the baseline criteria, if the displayed value is less than or equal to the baseline, the card will pass.

Q-Card's card opacity tester includes the tester, power supply, calibration/reference cards, calibration certificate and instructions.

The card opacity tester is designed to perform this test according to the following standards:

**Mastercard CQM**  
**ISO/IEC 7810**  
**ISO/IEC 10373-1**

# Ordering Details


| Part #     | Description                                |
|------------|--|
| 905703-2   | Opacity Tester                             |
| 905703-CAL | Equipment Calibration                      |
| W82-SK-846 | Black Opaque Reference Card (BORC)         |
| W82-ORC-01 | Opacity Reference Material Card (ORM-7810) |

# Specifications

## Weight

- 1 pound

# Dimensions



301 Reagan Street  
Sunbury PA 17801 USA  
Phone 570.286.7447  
Fax 570.286.2649  
[www.q-card.com](http://www.q-card.com)

Q-Card is



ISO 9001  
Compliant

800-717-8007